Chemwatch Material Safety Data Sheet

Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 1 of 10

Section 1 - CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NAME

Dy-Mark Zinc-Gal Galvanising Spray

SYNONYMS

"cold galvanizing aerosol spray paint zinc rich"

PROPER SHIPPING NAME

AEROSOLS

PRODUCT USE

■ Application is by spray atomisation from a hand held aerosol pack. Galvanising spray.

SUPPLIER

Company: Dy- Mark Pty Ltd Address: 89 Formation Street Wacol QLD, 4076 Australia


Telephone: +61 7 3271 2222 Emergency Tel:0403 186 708 Fax: +61 7 3271 2751 Email: info@dymark.com.au

Section 2 - HAZARDS IDENTIFICATION

STATEMENT OF HAZARDOUS NATURE

DANGEROUS GOODS. NON-HAZARDOUS SUBSTANCE. According to NOHSC Criteria, and ADG Code. CONSIDERED A DANGEROUS MIXTURE ACCORDING TO DIRECTIVE 1999/45/EC AND ITS AMENDMENTS. CONSIDERED A HAZARDOUS SUBSTANCE ACCORDING TO OSHA 29 CFR 1910.1200.

CHEMWATCH HAZARD RATINGS







RISK

- Extremely flammable.
- Risk of explosion if heated under confinement.
- Very toxic to aquatic organisms, may cause long- term adverse effects in the aquatic environment.
- Vapours may cause drowsiness and dizziness.

SAFETY

- · Keep away from sources of ignition. No smoking.
- Do not breathe gas/fumes/vapour/spray.
- · Avoid contact with skin.
- · Avoid contact with eyes.

Chemwatch Material Safety Data Sheet Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 2 of 10 Section 2 - HAZARDS IDENTIFICATION

- Inhalation and/or skin contact may produce health damage*.
- Ingestion may produce serious health damage*.
- Cumulative effects may result following exposure*.
- May produce discomfort of the respiratory system and skin*.
- Eye contact may produce serious damage*.
- May be harmful to the foetus/ embryo*.
- Repeated exposure potentially causes skin dryness and cracking*.
- * (limited evidence).

- · Wear suitable gloves.
- · Wear eye/face protection.
- · Use only in well ventilated areas.
- · Keep container in a well ventilated place.
- · Avoid exposure obtain special instructions before use.
- · Do not empty into drains.
- · To clean the floor and all objects contaminated by this material, use water and detergent.
- · Keep container tightly closed.
- · This material and its container must be disposed of in a safe way.
- · Take off immediately all contaminated clothing.
- In case of contact with eyes, rinse with plenty of water and contact Doctor or Poisons Information Centre.
- · Use appropriate container to avoid environmental contamination.
- · Avoid release to the environment. Refer to special instructions/Safety data sheets.
- · This material and its container must be disposed of as hazardous waste.

Section 3 - COMPOSITION / INFORMATION ON INGREDIENTS

NAME CAS RN % zinc powder 7440-66-6 30-60 naphtha petroleum, heavy, hydrodesulfurised 64742-82-1. 10-30 dimethyl ether 115-10-6 20-40

Section 4 - FIRST AID MEASURES

SWALLOWED

- · Avoid giving milk or oils.
- · Avoid giving alcohol.

Not considered a normal route of entry.

· If spontaneous vomiting appears imminent or occurs, hold patient's head down, lower than their hips to help avoid possible aspiration of vomitus.

- If aerosols come in contact with the eyes:
- Immediately hold the eyelids apart and flush the eye continuously for at least 15 minutes with fresh running water.
- · Ensure complete irrigation of the eye by keeping eyelids apart and away from eye and moving the eyelids by occasionally lifting the upper and lower lids.
- · Transport to hospital or doctor without delay.
- · Removal of contact lenses after an eye injury should only be undertaken by skilled personnel.

SKIN

- If solids or aerosol mists are deposited upon the skin:
- Flush skin and hair with running water (and soap if available).
- · Remove any adhering solids with industrial skin cleansing cream.
- · DO NOT use solvents.
- Seek medical attention in the event of irritation.

- If aerosols, fumes or combustion products are inhaled:
- Remove to fresh air

Chemwatch Material Safety Data Sheet Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 3 of 10 Section 4 - FIRST AID MEASURES

- · Lay patient down. Keep warm and rested.
- Prostheses such as false teeth, which may block airway, should be removed, where possible, prior to initiating first aid procedures.
- If breathing is shallow or has stopped, ensure clear airway and apply resuscitation, preferably with a demand valve resuscitator, bag-valve mask device, or pocket mask as trained. Perform CPR if necessary.

NOTES TO PHYSICIAN

- For acute or short term repeated exposures to petroleum distillates or related hydrocarbons:
- Primary threat to life, from pure petroleum distillate ingestion and/or inhalation, is respiratory failure.
- Patients should be quickly evaluated for signs of respiratory distress (e.g. cyanosis, tachypnoea, intercostal retraction, obtundation) and given oxygen. Patients with inadequate tidal volumes or poor arterial blood gases (pO2 50 mm Hg) should be intubated.
- Arrhythmias complicate some hydrocarbon ingestion and/or inhalation and electrocardiographic evidence of myocardial injury has been reported; intravenous lines and cardiac monitors should be established in obviously symptomatic patients. The lungs excrete inhaled solvents, so that hyperventilation improves clearance.
- A chest x-ray should be taken immediately after stabilisation of breathing and circulation to document aspiration and detect the presence of pneumothorax.

Treat symptomatically.

for lower alkyl ethers:

BASIC TREATMENT

- · Establish a patent airway with suction where necessary.
- · Watch for signs of respiratory insufficiency and assist ventilation as necessary.
- Administer oxygen by non-rebreather mask at 10 to 15 l/min.
- · A low-stimulus environment must be maintained.
- · Absorption of zinc compounds occurs in the small intestine.
- · The metal is heavily protein bound.
- · Elimination results primarily from faecal excretion.
- The usual measures for decontamination (Ipecac Syrup, lavage, charcoal or cathartics) may be administered, although patients usually have sufficient vomiting not to require them.

Section 5 - FIRE FIGHTING MEASURES

EXTINGUISHING MEDIA

- SMALL FIRE:
- · Water spray, dry chemical or CO2

LARGE FIRE:

· Water spray or fog.

FIRE FIGHTING

- Alert Fire Brigade and tell them location and nature of hazard.
- May be violently or explosively reactive.
- · Wear breathing apparatus plus protective gloves.
- · Prevent, by any means available, spillage from entering drains or water course.

FIRE/EXPLOSION HAZARD

- · Liquid and vapour are highly flammable.
- · Severe fire hazard when exposed to heat or flame.
- · Vapour forms an explosive mixture with air.
- Severe explosion hazard, in the form of vapour, when exposed to flame or spark.

Combustion products include: carbon monoxide (CO), carbon dioxide (CO2), other pyrolysis products typical of burning organic material

Contains low boiling substance: Closed containers may rupture due to pressure buildup under fire conditions.

FIRE INCOMPATIBILITY

- Reacts with acids producing flammable / explosive hydrogen (H2) gas.
- Avoid contamination with oxidising agents i.e. nitrates, oxidising acids, chlorine bleaches, pool chlorine etc. as ignition may result.

HAZCHEM

2YF

Chemwatch Material Safety Data Sheet

Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 4 of 10

Section 6 - ACCIDENTAL RELEASE MEASURES

MINOR SPILLS

- · Clean up all spills immediately.
- · Avoid breathing vapours and contact with skin and eyes.
- · Wear protective clothing, impervious gloves and safety glasses.
- Shut off all possible sources of ignition and increase ventilation.

MAJOR SPILLS

- · After clean up operations, decontaminate and launder all protective clothing and equipment before storing and re-using.
- Remove leaking cylinders to a safe place if possible.
- Release pressure under safe, controlled conditions by opening the valve.
- DO NOT exert excessive pressure on valve; DO NOT attempt to operate damaged valve.
- · Clear area of personnel and move upwind.
- · Alert Fire Brigade and tell them location and nature of hazard.
- · May be violently or explosively reactive.
- · Wear breathing apparatus plus protective gloves.

Personal Protective Equipment advice is contained in Section 8 of the MSDS.

Section 7 - HANDLING AND STORAGE

PROCEDURE FOR HANDLING

- · Avoid all personal contact, including inhalation.
- · Wear protective clothing when risk of exposure occurs.
- · Use in a well-ventilated area.
- · Prevent concentration in hollows and sumps.

SUITABLE CONTAINER

- CARE: Packing of high density product in light weight metal or plastic packages may result in container collapse with product release.
- · Heavy gauge metal packages / Heavy gauge metal drums.
- Aerosol dispenser.
- · Check that containers are clearly labelled.

STORAGE INCOMPATIBILITY

- Avoid reaction with oxidising agents.
- · Reacts slowly with water.
- · CAUTION contamination with moisture will liberate explosive hydrogen gas, causing pressure build up in sealed containers.
- Reacts violently with caustic soda, other alkalies generating heat, highly flammable hydrogen gas.
- If alkali is dry, heat generated may ignite hydrogen if alkali is in solution may cause violent foaming.
- · Segregate from alcohol, water.
- · Reacts with acids producing flammable / explosive hydrogen (H2) gas.

STORAGE REQUIREMENTS

- Keep dry to avoid corrosion of cans. Corrosion may result in container perforation and internal pressure may eject contents of can.
- Store in original containers in approved flammable liquid storage area.
- DO NOT store in pits, depressions, basements or areas where vapours may be trapped.
- · No smoking, naked lights, heat or ignition sources.
- Keep containers securely sealed. Contents under pressure.

Section 8 - EXPOSURE CONTROLS / PERSONAL PROTECTION

EXPOSURE CONTROLS

Chemwatch Material Safety Data Sheet

Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 5 of 10

Section 8 - EXPOSURE CONTROLS / PERSONAL PROTECTION

Source	Material	TWA ppm	TWA mg/m³	STEL ppm	STEL mg/m³	Peak ppm	Peak mg/m³	TWA F/CC	Notes
Australia Exposure Standards	Dy- Mark Zinc- Gal Galvanising Spray (White spirits)		790						(see Chapter 16)
Australia Exposure Standards	zinc powder (Inspirable dust (not otherwise classified))		10						
Australia Exposure Standards	naphtha petroleum, heavy, hydrodesulfurised (Petrol (gasoline))		900						(see Chapter 16)
Australia Exposure Standards	dimethyl ether (Dimethyl ether)	400	760	500	950				

PERSONAL PROTECTION









RESPIRATOR

•Type AX Filter of sufficient capacity. (AS/NZS 1716 & 1715, EN 143:2000 & 149:2001, ANSI Z88 or national equivalent)

EYE

■ No special equipment for minor exposure i.e. when handling small quantities.

OTHERWISE: For potentially moderate or heavy exposures:

- · Safety glasses with side shields.
- NOTE: Contact lenses pose a special hazard; soft lenses may absorb irritants and ALL lenses concentrate them.

HANDS/FEET

- No special equipment needed when handling small quantities.
- OTHERWISE:
- · For potentially moderate exposures:
- Wear general protective gloves, eg. light weight rubber gloves.

OTHER

■ No special equipment needed when handling small quantities.

OTHERWISE:

- Overalls.
- · Skin cleansing cream.
- · Eyewash unit.
- · Do not spray on hot surfaces.
- The clothing worn by process operators insulated from earth may develop static charges far higher (up to 100 times) than the minimum ignition energies for various flammable gas-air mixtures. This holds true for a wide range of clothing materials including cotton.
- Avoid dangerous levels of charge by ensuring a low resistivity of the surface material worn outermost. BRETHERICK: Handbook of Reactive Chemical Hazards.

ENGINEERING CONTROLS

■ Engineering controls are used to remove a hazard or place a barrier between the worker and the hazard. Well-designed engineering controls can be highly effective in protecting workers and will typically be independent of worker interactions to provide this high level of protection.

The basic types of engineering controls are:

Process controls which involve changing the way a job activity or process is done to reduce the risk.

Enclosure and/or isolation of emission source which keeps a selected hazard "physically" away from the worker and ventilation that strategically "adds" and "removes" air in the work environment.

Chemwatch Material Safety Data Sheet

Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 6 of 10

Not Available

Section 9 - PHYSICAL AND CHEMICAL PROPERTIES

APPEARANCE

■ Supplied as an aerosol pack. Contents under PRESSURE. Grey to silver liquid; does not mix with water.

PHYSICAL PROPERTIES

Liquid. Gas.

Does not mix with water.

State Liquid Molecular Weight Not Applicable Not Available Melting Range (°C) Viscosity Not Available Not Available Solubility in water (g/L) **Immiscible** Boiling Range (°C) Flash Point (°C) - 41 (propellant) pH (1% solution) Not Applicable Decomposition Temp (°C) Not Available pH (as supplied) Not Applicable Autoignition Temp (°C) Not Available Vapour Pressure (kPa) Not Available Upper Explosive Limit (%) Not Available Specific Gravity (water=1) Not Available Lower Explosive Limit (%) Not Available Relative Vapour Density Not Available (air=1)

Volatile Component (%vol) Not Available Evaporation Rate

dimethyl ether

log Kow (Sangster 1997):

Section 10 - STABILITY AND REACTIVITY

CONDITIONS CONTRIBUTING TO INSTABILITY

- Elevated temperatures.
- Presence of open flame.
- Product is considered stable.
- · Hazardous polymerisation will not occur.

For incompatible materials - refer to Section 7 - Handling and Storage.

Section 11 - TOXICOLOGICAL INFORMATION

POTENTIAL HEALTH EFFECTS

ACUTE HEALTH EFFECTS

SWALLOWED

■ Accidental ingestion of the material may be harmful; animal experiments indicate that ingestion of less than 150 gram may be fatal or may produce serious damage to the health of the individual.

Not normally a hazard due to physical form of product.

Considered an unlikely route of entry in commercial/industrial environments.

Ingestion of petroleum hydrocarbons can irritate the pharynx, oesophagus, stomach and small intestine, and cause swellings and ulcers of the mucous. Symptoms include a burning mouth and throat; larger amounts can cause nausea and vomiting, narcosis, weakness, dizziness, slow and shallow breathing, abdominal swelling, unconsciousness and convulsions. Damage to the heart muscle can produce heart beat irregularities, ventricular fibrillation (fatal) and ECG changes. The central nervous system can be depressed. Light species can cause a sharp tingling of the tongue and cause loss of sensation there. Aspiration can cause cough, gagging, pneumonia with swelling and bleeding.

EYE

■ There is some evidence to suggest that this material can cause eye irritation and damage in some persons.

Not considered to be a risk because of the extreme volatility of the gas.

Eye contact with alkyl ethers (vapour or liquid) may produce irritation, redness and tears.

Direct eye contact with petroleum hydrocarbons can be painful, and the corneal epithelium may be temporarily damaged. Aromatic species can cause irritation and excessive tear secretion.

Chemwatch Material Safety Data Sheet Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 7 of 10 Section 11 - TOXICOLOGICAL INFORMATION

SKIN

■ The material may accentuate any pre-existing dermatitis condition.

Repeated exposure may cause skin cracking, flaking or drying following normal handling and use.

Spray mist may produce discomfort.

Alkyl ethers may defat and dehydrate the skin producing dermatoses. Absorption may produce headache, dizziness, and central nervous system depression.

Open cuts, abraded or irritated skin should not be exposed to this material.

Entry into the blood-stream, through, for example, cuts, abrasions or lesions, may produce systemic injury with harmful effects. Examine the skin prior to the use of the material and ensure that any external damage is suitably protected.

Skin contact with the material may be harmful; systemic effects may result following absorption.

There is some evidence to suggest that the material may cause mild but significant inflammation of the skin either following direct contact or after a delay of some time. Repeated exposure can cause contact dermatitis which is characterised by redness, swelling and blistering.

Aromatic hydrocarbons may produce sensitivity and redness of the skin. They are not likely to be absorbed into the body through the skin but branched species are more likely to.

INHALED

■ Inhalation of vapours may cause drowsiness and dizziness. This may be accompanied by sleepiness, reduced alertness, loss of reflexes, lack of co-ordination, and vertigo.

Inhalation of aerosols (mists, fumes), generated by the material during the course of normal handling, may be damaging to the health of the individual.

There is some evidence to suggest that the material can cause respiratory irritation in some persons. The body's response to such irritation can cause further lung damage.

The acute toxicity of inhaled alkylbenzenes is best described by central nervous system depression. As a rule, these compounds may also act as general anaesthetics.<</>>.

Inhalation of toxic gases may cause:

- · Central Nervous System effects including depression, headache, confusion, dizziness, stupor, coma and seizures;
- · respiratory: acute lung swellings, shortness of breath, wheezing, rapid breathing, other symptoms and respiratory arrest;
- · heart: collapse, irregular heartbeats and cardiac arrest;
- gastrointestinal: irritation, ulcers, nausea and vomiting (may be bloody), and abdominal pain.

Inhaling high concentrations of mixed hydrocarbons can cause narcosis, with nausea, vomiting and lightheadedness. Low molecular weight (C2-C12) hydrocarbons can irritate mucous membranes and cause incoordination, giddiness, nausea, vertigo, confusion, headache, appetite loss, drowsiness, tremors and stupor. Massive exposures can lead to severe central nervous system depression, deep coma and death. Convulsions can occur due to brain irritation and/or lack of oxygen. Permanent scarring may occur, with epileptic seizures and brain bleeds occurring months after exposure. Respiratory system effects include inflammation of the lungs with oedema and bleeding. Lighter species mainly cause kidney and nerve damage; the heavier paraffins and olefins are especially irritant to the respiratory system. Alkenes produce pulmonary oedema at high concentrations. Liquid paraffins may produce sensation loss and depressant actions leading to weakness, dizziness, slow and shallow respiration, unconsciousness, convulsions and death. C5-7 paraffins may also produce multiple nerve damage. Aromatic hydrocarbons accumulate in lipid rich tissues (typically the brain, spinal cord and peripheral nerves) and may produce functional impairment manifested by nonspecific symptoms such as nausea, weakness, fatigue, vertigo; severe exposures may produce inebriation or unconsciousness. Many of the petroleum hydrocarbons can sensitise the heart and may cause ventricular fibrillation, leading to death.

Central nervous system (CNS) depression may include general discomfort, symptoms of giddiness, headache, dizziness, nausea, anaesthetic effects, slowed reaction time, slurred speech and may progress to unconsciousness. Serious poisonings may result in respiratory depression and may be fatal.

Material is highly volatile and may quickly form a concentrated atmosphere in confined or unventilated areas. Vapour is heavier than air and may displace and replace air in breathing zone, acting as a simple asphyxiant.

Inhalation of high concentrations of gas/vapour causes lung irritation with coughing and nausea, central nervous depression with headache and dizziness, slowing of reflexes, fatigue and inco-ordination.

Exposure to white spirit may cause nausea and vertigo.

WARNING: Intentional misuse by concentrating/inhaling contents may be lethal.

CHRONIC HEALTH EFFECTS

■ Substance accumulation, in the human body, may occur and may cause some concern following repeated or long-term occupational exposure.

Principal route of occupational exposure to the gas is by inhalation.

Constant or exposure over long periods to mixed hydrocarbons may produce stupor with dizziness, weakness and visual disturbance, weight loss and anaemia, and reduced liver and kidney function. Skin exposure may result in drying and cracking and redness of the skin. Chronic exposure to lighter hydrocarbons can cause nerve damage, peripheral neuropathy, bone marrow dysfunction and psychiatric disorders as well as damage the liver and kidneys.

Immersion of the hands and forearms in white spirits may quickly result in inflammation of the skin and follicles. Workers exposed to white spirit have reported nausea and vomiting and one worker has been reported to develop aplastic anaemia, bone marrow depression and this person later died from septicaemia. Bone marrow depression may be due to the presence of compounds toxic to it, for example, benzene.

Chronic exposure to alkyl ethers may result in loss of appetite, excessive thirst, fatigue, and weight loss.

Metallic dusts generated by the industrial process give rise to a number of potential health problems. The larger particles, above 5 micron, are nose and throat irritants. Smaller particles however, may cause lung deterioration. Particles of less than

Chemwatch Material Safety Data Sheet Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 8 of 10 Section 11 - TOXICOLOGICAL INFORMATION

1.5 micron can be trapped in the lungs and, dependent on the nature of the particle, may give rise to further serious health consequences.

Chronic solvent inhalation exposures may result in nervous system impairment and liver and blood changes. [PATTYS].

TOXICITY AND IRRITATION

■ Not available. Refer to individual constituents.

Section 12 - ECOLOGICAL INFORMATION

Very toxic to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

This material and its container must be disposed of as hazardous waste.

Avoid release to the environment.

Refer to special instructions/ safety data sheets.

Ecotoxicity

Persistence: Persistence: Air Bioaccumulation Mobility Ingredient Water/Soil

No Data IOW zinc powder No Data

Available Available naphtha petroleum, heavy, No Data No Data hydrodesulfurised Available Available dimethyl ether LOW No Data

LOW HIGH

Available

Section 13 - DISPOSAL CONSIDERATIONS

- DO NOT allow wash water from cleaning or process equipment to enter drains.
- It may be necessary to collect all wash water for treatment before disposal.
- · In all cases disposal to sewer may be subject to local laws and regulations and these should be considered first.
- · Where in doubt contact the responsible authority.
- · Consult State Land Waste Management Authority for disposal.
- Discharge contents of damaged aerosol cans at an approved site.
- · Allow small quantities to evaporate.
- · DO NOT incinerate or puncture aerosol cans.

Section 14 - TRANSPORTATION INFORMATION





Labels Required: FLAMMABLE GAS

HAZCHEM:

2YE (ADG7)

Land Transport UNDG:

Class or division 2.1 Subsidiary risk: None 1950 UN packing group: None UN No ·

Shipping Name: AEROSOLS

Air Transport IATA:

ICAO/IATA Class: 2.1 ICAO/IATA Subrisk: None UN/ID Number: 1950 Packing Group:

Special provisions: A145

Cargo Only

Packing Instructions: 203 Maximum Qty/Pack: 150 kg

Chemwatch Material Safety Data Sheet

Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 9 of 10

Section 14 - TRANSPORTATION INFORMATION

Passenger and Cargo Passenger and Cargo

Packing Instructions: 203 Maximum Qty/Pack: 75 kg
Passenger and Cargo Limited Quantity Passenger and Cargo Limited Quantity

Packing Instructions: Y203 Maximum Qty/Pack: 30 kg G

Shipping name: AEROSOLS

Maritime Transport IMDG:

IMDG Class:2IMDG Subrisk:SP63UN Number:1950Packing Group:None

EMS Number: F-D,S-U Special provisions: 63 190 277 327 344 959

Limited Quantities: See SP277 Marine Pollutant: Yes

Shipping name: AEROSOLS

Section 15 - REGULATORY INFORMATION

POISONS SCHEDULE

None

REGULATIONS

Regulations for ingredients

zinc powder (CAS: 7440-66-6) is found on the following regulatory lists;

"Australia - Australian Capital Territory - Environment Protection Regulation: Ambient environmental standards (AQUA/1 to 6 - inorganic chemicals)", "Australia - Australian Capital Territory - Environment Protection Regulation: Ambient environment Protection Regulation: Ambient environmental standards (Domestic water supply - inorganic chemicals)", "Australia - Australian Capital Territory - Environment Protection Regulation: Ambient environmental standards (IRRIG - inorganic chemicals)", "Australia - Australian Capital Territory - Environment Protection Regulation: Ambient environmental standards (STOCK - inorganic chemicals)", "Australia - Australian Capital Territory - Environment Protection Regulation: Pollutants entering waterways taken to cause environmental harm (Aquatic habitat)", "Australia - Australian Capital Territory - Environment Protection Regulation: Pollutants entering waterways taken to cause environmental harm (Domestic water supply quality)", "Australia - Australian Capital Territory - Environment Protection Regulation: Pollutants entering waterways taken to cause environmental harm (IRRIG)", "Australia - Australian Capital Territory - Environment Protection Regulation: Pollutants entering waterways taken to cause environmental harm (STOCK)", "Australia Hazardous Substances", "Australia High Volume Industrial Chemical List (HVICL)", "Australia Inventory of Chemical Substances (AICS)", "WHO Guidelines for Drinking-water Quality - Chemicals for which guideline values have not been established"

naphtha petroleum, heavy, hydrodesulfurised (CAS: 64742-82-1,8052-41-3) is found on the following regulatory lists;

"Australia Hazardous Substances", "Australia Inventory of Chemical Substances (AICS)", "International Council of Chemical Associations (ICCA) - High Production Volume List"

dimethyl ether (CAS: 115-10-6,157621-61-9) is found on the following regulatory lists;

"Australia Exposure Standards", "Australia Hazardous Substances", "Australia Inventory of Chemical Substances (AICS)",

"International Council of Chemical Associations (ICCA) - High Production Volume List"

No data for Dy-Mark Zinc-Gal Galvanising Spray (CW: 4606-82)

Section 16 - OTHER INFORMATION

INGREDIENTS WITH MULTIPLE CAS NUMBERS

Ingredient Name CAS

naphtha petroleum, heavy, hydrodesulfurised 64742-82-1, 8052-41-3 dimethyl ether 115-10-6, 157621-61-9

■ Classification of the preparation and its individual components has drawn on official and authoritative sources as well as independent review by the Chemwatch Classification committee using available literature references.

A list of reference resources used to assist the committee may be found at:

www.chemwatch.net/references.

Chemwatch Material Safety Data Sheet Issue Date: 3-Oct-2011

X9317SP

Hazard Alert Code: EXTREME

CHEMWATCH 4606-82 Version No:9 Page 10 of 10 Section 16 - OTHER INFORMATION

■ The (M)SDS is a Hazard Communication tool and should be used to assist in the Risk Assessment. Many factors determine whether the reported Hazards are Risks in the workplace or other settings.

This document is copyright. Apart from any fair dealing for the purposes of private study, research, review or criticism, as permitted under the Copyright Act, no part may be reproduced by any process without written permission from CHEMWATCH. TEL (+61 3) 9572 4700.

Issue Date: 3-Oct-2011 Print Date: 1-Feb-2012

This is the end of the MSDS.