






5 DRAWER TOOL CHEST UUB10



ULTIMATE
STORAGE




NO	PART NAME	PCS
①	MDF BENCH TOP	1 PCS
②	CABINET BODY	1 PCS
③	CASTER (WITH BRAKES)	2 PCS
④	CASTER	2 PCS
⑤	M8 x 15mm PAN HEAD HEX BOLT	16 PCS



Step 1.

Place the Cabinet Body (2) on the ground, upside down. Fix the castors (With Brakes) (3) on one side of the Cabinet Body and fix the Castors (4) on the other side, using the M8 x 15mm Pan Head Hex Bolts (5) provided.



Step 2.

Recover the cabinet to upright position. Place the MDF Bench Top (1) on the top of the Cabinet Body.